



RCA Name Slurry pump seal leakage  
 Report Number 2012-B201  
 Report Date 12/3/2012  
 RCA Owner C. Eckert

## Root Cause Analysis Report

### Problem Statement

**Focal Point** 20 hours of production outage (Pump seal replacement)

#### When

Start Date 11/21/2012 End Date 11/22/2012  
 Start Time 14:00 End Time 10:00  
 Unique Timing 2 weeks after pump was installed as part of capital project

#### Where

Business Unit Performance products  
 Location Crump, Michigan, USA  
 System Reaction step  
 Component P-105

#### Actual Impact

|                             |  | Cost                |
|-----------------------------|--|---------------------|
| Safety                      | None   | \$0.00              |
| Environmental               | 500 lbs of methyl bad-stuff leaked into dike; contained  | \$0.00              |
| Revenue                     | Lost profit due to 20 hours downtime (Plant is sold out).<br>Delays in getting product to market | \$100,000.00        |
| Cost                        | Pump repair; labor & parts   | \$15,000.00         |
| Cost                        | Clean up   | \$1,500.00          |
| Environmental               | Disposal of spilled methyl bad-stuff   | \$3,000.00          |
| <b>Actual Impact Total:</b> |  | <b>\$119,500.00</b> |

Frequency 1 times per week

Frequency Notes Pump has been replaced twice in last 2 weeks, so total cost so far is ~\$240k.

#### Potential Impact

|                                |  |                       |
|--------------------------------|--|-----------------------|
| Safety                         | Potential exposure to skin irritant from leaking seal  | \$0.00                |
| Revenue                        | Annualized loss at current rate. Losses could grow if demand grows per expected market projections | \$5,200,000.00        |
| <b>Potential Impact Total:</b> |  | <b>\$5,200,000.00</b> |

# Report Summaries

## **Executive Summary**

The repeat failure of the new P-105 slurry pump has caused repeat, unplanned shutdowns resulting in lost profit and excessive expenditures due to seal leaks. The slurry contains 50% methyl bad stuff which is an environmentally regulated chemical and requires the pump to be shut down upon detection of a leak greater than 2kg/hr causing production losses amounting to \$240,000 thus far. These losses will increase as product demand grows. The project team was under cost- and timing- pressure, and specified a seal that was not suitable for this service.

In order to prevent repeat seal failures, the corrective action is to install a new type of seal and stuffing box capable of handling the solids. The preventive actions are to integrate a reliability review with all new capital projects and to require the area reliability engineer to provide design criteria to the project teams for special, known process and equipment requirements.

## **Cause and Effect Summary**

The unplanned shutdown was caused by a seal leak of slurry pump P-105. The seal leak was the result of a single mechanical seal being installed in slurry service. Single mechanical seals with discharge recirc flushes in slurry service fail due to solids depositing on the seal faces. Deposits open the seal faces as the pumped liquid evaporates across the seal faces, leaving solids behind. This opens the seal faces creating increasingly worse seal leakage. The single mechanical seal was installed because the project team didn't know it was not the best choice, and because it was inexpensive. The team didn't know it wasn't the best choice because they didn't seek reliability input and because no one gave them input upfront as to the most effective design criteria for the process and equipment requirements. The missing input was caused by no step, or requirement, in the capital project guidelines to integrate reliability input. The project team also went with the single seal because they were looking to cut costs due to budget constraints imposed on them by the business and because they were projected to be over budget. They were also in a rush to complete the project in order to get the product to market more quickly.

## Solutions

| <b>ID</b> | <b>Label</b>    | <b>Description</b>  |                 |             |
|-----------|-----------------|---|-----------------|-------------|
| 1         | <b>Solution</b> | Replace single seal with double mechanical seal   |                 |             |
|           | <b>Cause</b>    | Single mechanical seal on pump  |                 |             |
|           | <b>Note</b>     |   |                 |             |
|           | <b>Assigned</b> | Bill Wilson   | <b>Criteria</b> | Pass        |
|           | <b>Due</b>      | 12/26/2012  | <b>Status</b>   | Approved    |
|           | <b>Term</b>     | Short   | <b>Cost</b>     | \$10,000.00 |
|           |                 |   |                 |             |
| 2         | <b>Solution</b> | Modify capital project steps to include R&M review  |                 |             |
|           | <b>Cause</b>    | New pump did not receive reliability review   |                 |             |
|           | <b>Note</b>     |   |                 |             |
|           | <b>Assigned</b> | Sue Young   | <b>Criteria</b> | Pass        |
|           | <b>Due</b>      | 2/3/2013  | <b>Status</b>   | Approved    |
|           | <b>Term</b>     | Medium  | <b>Cost</b>     | \$800.00    |
|           |                 |   |                 |             |
| 3         | <b>Solution</b> | Modify capital project steps to have reliability engineer provide list of key design criteria for new equipment |                 |             |
|           | <b>Cause</b>    | Design choice by capital project team   |                 |             |
|           | <b>Note</b>     |   |                 |             |
|           | <b>Assigned</b> | Bill Wilson   | <b>Criteria</b> | Pass        |
|           | <b>Due</b>      | 2/3/2013  | <b>Status</b>   | Approved    |
|           | <b>Term</b>     | Medium  | <b>Cost</b>     | \$0.00      |
|           |                 |   |                 |             |
| 4         | <b>Solution</b> | Install seal-less pump  |                 |             |
|           | <b>Cause</b>    | Single mechanical seal on pump  |                 |             |
|           | <b>Note</b>     | Not confident that seal-less pump would be able to handle the large solids present                              |                 |             |
|           | <b>Assigned</b> | Choose  | <b>Criteria</b> | Fail        |
|           | <b>Due</b>      |   | <b>Status</b>   | Identified  |
|           | <b>Term</b>     | Choose  | <b>Cost</b>     | \$0.00      |
|           |                 |   |                 |             |
| 5         | <b>Solution</b> | Replace conventional stuffing box with taper bore stuffing box  |                 |             |
|           | <b>Cause</b>    | Conventional stuffing box installed   |                 |             |

|                 |            |                 |            |
|-----------------|------------|-----------------|------------|
| <b>Note</b>     |            |                 |            |
| <b>Assigned</b> | Choose     | <b>Criteria</b> | Pass       |
| <b>Due</b>      | 12/26/2012 | <b>Status</b>   | Selected   |
| <b>Term</b>     | Short      | <b>Cost</b>     | \$2,000.00 |

## Team

| <b>ID</b> | <b>Label</b>      | <b>Description</b>       | <b>Label</b>     | <b>Description</b> |
|-----------|-------------------|--------------------------|------------------|--------------------|
| 1         | <b>First Name</b> | Bill                     | <b>Last Name</b> | Wilson             |
|           | <b>Phone (1)</b>  |                          | <b>Phone (2)</b> |                    |
|           | <b>Role</b>       | Rel eng                  | <b>Group</b>     |                    |
|           | <b>Email</b>      | bw@stuff.com             |                  |                    |
| 2         | <b>First Name</b> | Sue                      | <b>Last Name</b> | Young              |
|           | <b>Phone (1)</b>  |                          | <b>Phone (2)</b> |                    |
|           | <b>Role</b>       | Proj eng                 | <b>Group</b>     |                    |
|           | <b>Email</b>      | sy@stuff.com             |                  |                    |
| 3         | <b>First Name</b> | Dan                      | <b>Last Name</b> | Valerio            |
|           | <b>Phone (1)</b>  |                          | <b>Phone (2)</b> |                    |
|           | <b>Role</b>       | Machinist                | <b>Group</b>     |                    |
|           | <b>Email</b>      | dv@stuff.com             |                  |                    |
| 4         | <b>First Name</b> | Chris                    | <b>Last Name</b> | Eckert             |
|           | <b>Phone (1)</b>  |                          | <b>Phone (2)</b> |                    |
|           | <b>Role</b>       |                          | <b>Group</b>     |                    |
|           | <b>Email</b>      | chris.eckert@sologic.com |                  |                    |

## Evidence

| ID | Label                              | Description  |
|----|------------------------------------|--|
| 1  | <b>Evidence</b><br><b>Cause(s)</b> | visual observation<br>Single seal ordered with new pump<br>Single mechanical seal on pump<br>Pump was running<br>Pump P-105 seal leaking excessively<br>Solids stick to faces<br>Inexperienced project team<br>No clean, external seal flush<br>Pump not upgraded after installation<br>Solids in fluid accumulate on seal faces<br>Accumulated solids opens faces<br>Conventional stuffing box installed<br>Solids not flushed away<br>Face materials are the same<br>One face is stationary<br>Total turnaround time = 20 hours<br>1 hour to LOTO<br>1 hour to flush and drain<br>1 hr for LEO and disconnection<br>3 hours to reinstall<br>2 hours to de-LEO and recommission<br>12 hours to replace seal in shop |
|    | <b>Location</b>                    |  |
|    | <b>Link</b>                        |  |
|    | <b>Contributor</b>                 | Bill Wilson  |
|    | <b>Type</b>                        | Direct Observation   |
|    | <b>Quality</b>                     | ★★★★☆  |
| 2  | <b>Evidence</b><br><b>Cause(s)</b> | EH&S Manager statement<br>Desire to be in compliance with all environmental regulations<br>Pump handles regulated chemical<br>Desire to be good environmental stewards<br>Decision not to exceed allowable emissions<br>Pumped fluid is skin irritant<br>Leaking seal is safety hazard   |
|    | <b>Location</b>                    |  |
|    | <b>Link</b>                        |  |

**Contributor** Choose  
**Type** Direct Statement  
**Quality** ★★★★★

3 **Evidence** Project engineer statement

**Cause(s)** Reliability group never provided feedback  
No reliability personnel assigned to project team  
Single seal is relatively inexpensive  
Project team needed to save money  
Project team over-ran budget  
Design choice by capital project team  
Fast track Project  
Inexperienced project team  
No one recognized the need  
Capital projects group never asked  
Reliability input not required in project guidelines  
New pump did not receive reliability review  
No design standards for this application  
No information or knowledge to spec anything different  
Single seal ordered with new pump

**Location**

**Link**

**Contributor** Choose  
**Type** Direct Statement  
**Quality** ★★★★★

4 **Evidence** Seal mfg literature

**Cause(s)** Single mechanical seals unable to tolerate solids  
Accumulated solids opens faces  
Liquid vaporizes  
Small amount of pumped fluid leaks across seal faces  
Conventional stuffing boxes unable to effectively purge solids  
Seal faces run hotter than liquid boiling point  
Heat generated by seal face friction  
Inability to cool faces  
High friction coefficient  
One face is stationary  
One face rotates

**Location**

**Link** <http://www.flowserve.com/Products/Seals>

**Contributor** Chris Eckert  
**Type** Document  
**Quality** ★★★★★

5 **Evidence** Machinist statement  
**Cause(s)** Single seal is relatively inexpensive  
Single mechanical seal on pump  
Accumulated solids opens faces  
Pumped fluid contains solids  
Capital projects group never asked  
Pump not upgraded after installation  
No clean, external seal flush  
Solids stick to faces  
Conventional stuffing boxes unable to effectively purge solids

**Location**  
**Link**

**Contributor** Choose  
**Type** Direct Statement  
**Quality** ★★★★★

6 **Evidence** Operations Supv statement  
**Cause(s)** System under pressure  
Choose not to run with leaking seal  
Decision to repair pump P-105

**Location**  
**Link**

**Contributor** Choose  
**Type** Direct Statement  
**Quality** ★★★★★



# Actions & Chart Quality

Custom Actions - 1

| <b>ID</b> | <b>Label</b>     | <b>Description</b>                  |  |                 |
|-----------|------------------|-------------------------------------|--|-----------------|
| 149       | <b>Action</b>    | Determine type of stuffing box      |  |                 |
|           | <b>Cause</b>     | Conventional stuffing box installed |  |                 |
|           | <b>Assigned</b>  | Choose                              |  | <b>Due Date</b> |
|           | <b>Completed</b> | no                                  |  |                 |

Evidence - 1

Termination Points - 6

Cause Types - 0

Unconnected Causes - 0

Empty Cause Boxes - 0

# Notes

| <b>ID</b> | <b>Label</b> | <b>Description</b>   |
|-----------|--------------|--|
| 1         | <b>Note</b>  | Machinists checked clearances and tolerances, and all looked in accordance with spec |
|           | <b>Cause</b> | Seal Improperly installed?   |
| 2         | <b>Note</b>  | Speed to market was key to successful product launch                                 |
|           | <b>Cause</b> | Fast track Project   |
| 3         | <b>Note</b>  | Verified steps   |
|           | <b>Cause</b> | Seal Improperly installed?   |

**Chart Type Legend**

- ▶ Transitory
- Non-transitory
- Omission - Transitory
- Omission - Non-transitory
- ★ Focal Point
- Solution Implemented

