



RCA Name Metal Dust Flash Fires and Hydrogen Explosion
 Report Number CSB: No. 2011-4-I-TN
 Report Date 1/10/2012
 RCA Owner Chemical Safety Board/Hoeganaes Corporation

Root Cause Analysis Report

Problem Statement

Focal Point 2 Fatalities

When

Start Date 1/31/2011
 Start Time 5:00am
 Unique Timing After requesting that a motor be restarted

Where

Facility Hoeganaes Corporation: Gallatin, TN
 Component Bucket elevator # 12 and motor
 Other... Iron dust - 45 to 150 microns

Actual Impact

	Cost
Safety 2 Fatalities	
Revenue Unknown, but likely substantial	
Cost Unknown, but likely substantial	
Other... Publicity: Severe negative impact	
Other... Employee Confidence: Severe negative impact	
Actual Impact Total:	\$0.00

Frequency Notes Multiple flash fires occurred in the history of the plant, but none were fatal until 1/31/2011

Report Summaries

Cause and Effect Summary

On January 31, 2011 at around 5:00AM, the [company] experienced an incident that led to two fatalities. Two employees were severely burned in an iron dust fire. The employees were wearing fire protective clothing, however this was not adequate protection due to the temperature of the fire, the contact time with the fire, and the proximity of the employees to the fire.

The two employees had been sent to repair a belt conveyor motor that had tripped. Upon examination, the employees did not find an obvious problem. One employee radioed the control room to attempt to restart the motor. This triggered an iron dust fire that immediately engulfed the two workers.

When the motor was restarted, it caused vibration in the surrounding equipment. This vibration mobilized into the air a large amount of iron dust that had settled on the equipment and surrounding structures. This dust encountered an ignition source - likely exposed wiring for the motor - and immediately ignited. It is unknown why the wiring had been left exposed. The team also discovered that the motor was not grounded properly, which could have contributed to the ignition.

There are tons of iron dust throughout the entire facility. The facility was not designed according to dust management best practices and therefore has many flat surfaces that can gather dust in areas where cleaning is difficult.

The iron dust comes primarily from multiple places in the dust handling system that are not completely sealed. Also, dust comes from open conveyor systems. The dust collection system is down frequently due to mechanical failures.

There are regulatory gaps and loopholes which prevent oversight of this type of production facility.

Solutions

ID	Label	Description		
1	Solution	Identify and seal leaks in dust handling system.		
	Cause	Dust handling system not completely sealed		
	Note	Inspect the plant for contributors to airborne dust through seal leaks. Rank them, and work on eliminating the largest contributors.		
	Assigned	Hoeganaes Corporation	Criteria	Pass
	Due		Status	Selected
	Term	Medium	Cost	\$0.00
2	Solution	Replace with closed conveyers, or modify existing so they are enclosed		
	Cause	Open conveyers		
	Note	No notes		
	Assigned	Hoeganaes Corporation	Criteria	Pass
	Due		Status	Selected
	Term	Medium	Cost	\$0.00
3	Solution	Implement housekeeping practices and standards		
	Cause	Accumulated iron dust not cleaned up		
	Note	Housekeeping should become much easier once the sources of dust are identified and eliminated.		
	Assigned	Hoeganaes Corporation	Criteria	Pass
	Due		Status	Selected
	Term	Short	Cost	\$0.00
4	Solution	Conduct dyanamic analysis into dust collection system outages		
	Cause	Dust collection system frequently down		
	Note	The dust collection system has reliability problems. Complete a reliabilty assessment of the dust collection system and develop a plan to reduce the number and severity of outages.		
	Assigned	Hoeganaes Corporation	Criteria	Pass
	Due		Status	Selected
	Term	Short	Cost	\$0.00

5	Solution	Develop a plan to improve the dust accumulation properties of the plant design		
	Cause	Facility design susceptible to dust accumulation		
	Note	Utilize best practices for making a facility resilient to dust accumulation.		
	Assigned	Hoeganaes Corporation	Criteria	Pass
	Due		Status	Selected
	Term	Medium	Cost	\$0.00

7	Solution	Don't wait for regulatory agencies. Develop and apply standards internally.		
	Cause	Regulatory gaps (OSHA, NFPA, IFC)		
	Note	Proactively anticipate regulation and get in front of it. Conduct plant audits as if the regulations were in place.		
	Assigned	Hoeganaes Corporation	Criteria	Pass
	Due		Status	Selected
	Term	Short	Cost	\$0.00

8	Solution	Completely clean the facility from top to bottom.		
	Cause	Tons of iron dust throughout facility		
	Note	The facility needs a complete cleaning. This needs to happen in conjunction with a more effective housekeeping effort. This will likely be a one-time effort because as sources for dust are found and eliminated, less dust will accumulate.		
	Assigned	Hoeganaes Corporation	Criteria	Pass
	Due		Status	Selected
	Term	Short	Cost	\$0.00

9	Solution	Clean up area before beginning work		
	Cause	Iron dust on motor/elevator		
	Note	Work areas need to be clean and free from debris. Proximity to flammable iron dust was a major contributor to these two fatalities. Had the dust been removed before work began, the incident may not have occurred.		
	Assigned	Hoeganaes Corporation	Criteria	Pass
	Due		Status	Selected
	Term	Short	Cost	\$0.00

10	Solution	Inspect the site for wiring hazards and fix.		
	Cause	Exposed wiring		

Note Open J-boxes, exposed wiring, etc are not acceptable. All instances need to be identified and fixed as soon as possible.

Assigned Hoeganaes Corporation

Criteria Pass

Due

Status Selected

Term Short

Cost \$0.00

11 **Solution** Complete an audit of the facility to identify improper grounding. Ensure everything is properly grounded.

Cause Motor not properly grounded

Note The facility and it's components need to be properly grounded.

Assigned Hoeganaes Corporation

Criteria Pass

Due

Status Selected

Term Short

Cost \$0.00

12 **Solution** Conduct PJHAs to identify risks. Wear appropriate PPE per risks identified.

Cause Employees not protected

Note All employees need to conduct PJHAs prior to beginning a job. Make sure to identify and mitigate risks associated with any job.

Assigned Hoeganaes Corporation

Criteria Pass

Due

Status Selected

Term Short

Cost \$0.00

Team

ID	Label	Description	Label	Description
1	First Name	Brian	Last Name	Hughes
	Phone (1)	206-282-7703	Phone (2)	206-331-2569
	Role	Investigator	Group	
	Email	brian.hughes@sologic.com		
2	First Name	Hoeganaes Corporation	Last Name	
	Phone (1)		Phone (2)	
	Role		Group	
	Email			
3	First Name	Sheryl	Last Name	Jesse
	Phone (1)		Phone (2)	
	Role		Group	
	Email			

Evidence

ID	Label	Description
1	Evidence Cause(s)	CSB Video "Iron in the Fire", 1/05/2012 2 employees burned Severity of burns = High 2 employees positioned near ignition point Sufficient contact time Iron dust from multiple sources Iron dust ignited High temperatures Combustible iron dust cloud near motor Oxygen present Electric arc occurred (speculation) Ignition occurred near motor Employees were investigating motor shutdown Iron dust stirred up from motor/elevator surroundings Motor energized Iron dust on motor/elevator Motor/elevator vibrated Tons of iron dust throughout facility System started up Vibration occurs upon start up Dust handling system not completely sealed Open conveyers Accumulated iron dust not cleaned up Facility design susceptible to dust accumulation Regulatory gaps (OSHA, NFPA, IFC) Dust collection system frequently down
	Location	CSB Website
	Link	
	Contributor	Brian Hughes
	Type	Other
	Quality	
2	Evidence Cause(s)	CSB Hoeganaes Corporation Case Study 2 employees burned Severity of burns = High 2 employees positioned near ignition point Sufficient contact time Employees not protected Iron dust ignited

High temperatures
 FPC doesn't protect against large dust explosions
 Employees wear Fire Protective Clothing (FPC)
 Combustible iron dust cloud near motor
 Oxygen present
 Electric arc occurred (speculation)
 Ignition occurred near motor
 Employees were investigating motor shutdown
 Iron dust stirred up from motor/elevator surroundings
 Exposed wiring
 Motor not properly grounded
 Motor energized
 Iron dust on motor/elevator
 Motor/elevator vibrated
 Tons of iron dust throughout facility
 System started up
 Vibration occurs upon start up
 Dust handling system not completely sealed
 Open conveyers
 Accumulated iron dust not cleaned up
 Facility design susceptible to dust accumulation
 Regulatory gaps (OSHA, NFPA, IFC)
 Dust collection system frequently down

Location http://www.csb.gov/assets/document/CSB_Case_Study_Hoeganaes_Dec9_Final.pdf

Link

Contributor Brian Hughes

Type Document

Quality ★★☆☆☆

3 **Evidence** Statement - Sheryl

Cause(s) System started up
 Oxygen present

Location

Link

Contributor Sheryl Jesse

Type Document

Quality ★★★★★

